

Field Inspection Report - Vesta_Energy 650558_01/20/2017_VTI_External

Vessel Number	650558	Vessel Name	SEPARATOR	Province	Alberta
District	CENTRAL	LSD	10-15-040-27W4	Location	JOFFRE
Method	VTI	Access	External	Cleaning	Good
Inspection Date (mm/dd/yyyy)	01/20/2017	Inspection Interval (months)	60	Next Inspection (mm/dd/yyyy)	01/20/2022
CRN	W3897.213	Skid Number	PKG72272	Service	SWEET
Manway	No	Internal Coating	No	Status	In Service
MAWP (PSI)	1440	MAWP (kPa)	9928.51	Outstanding NCRs	0
MAWT (°C)	54.44	MAWT (°F)	130		

General

An Installation inspection of the Separator, was conducted as per procedure MWS-08. The Installation inspection includes checking the Separator and associated piping. The associated piping was secure and properly supported. No physical damage was observed from the transportation and installation.

Safety Valves

PSV P113028 Shell side. Set pressure: 1440 PSI / 9928.51 KPa. MAWP: 1440 PSI / 9928.51 KPa. Capacity: 10874 SCFM / 307.92 m3/min.

External Condition

All visible shell surfaces and nozzles appeared in good condition. The Name plate is intact and legible. The Separator has an Alberta CRN # and an ABSA A#. The separator supports, foundation, and external coating appear to be in good condition. The Associated piping, supports and components appear to be in good condition and alignment with no signs of leaks or defects present at the time of inspection. The separator has proper PSV protection and the PSV is properly installed and in the vertical position. There are no block valves in the relief path. The PSV was last serviced within the required ABSA_AB-506 interval guidelines. The next inspection interval was assigned

Internal Condition

Recommendations

Field Inspection Report - Vesta_Energy 650558_01/20/2017_VTI_External

No recommendations at this time.

Suitable to be returned to Service	Yes	Repairs complete (AB-40 attached)	N/A
Repairs are still required	No	Suggested Inspection interval (Months)	60
Daniel Walsh ABSA ISBPV: 000318 Inspector	Signature		01/24/2017 Date (mm/dd/yyyy)

Pictures

-No pictures for this inspection-	
-----------------------------------	--