ULTRASONIC CORROSION SURVEY REPORT

330, 4311-12 St. N.E.
Calgary, AB T2E 4P9
Bus: (403) 216-3485
Fax: (403) 216-3486
solutions@skystone.ca

Client:	ARC Resources	LSD:	100/01-01-111-11W6M	Bottom Hole Location:			
Owner ID:	A0573887	Unit:	Dawson Stock	Equipment:	Lineheater Coil		
PRN:	0573887	CRN:	P1236.21	Mfr.:	RUSHTON		
Mfr. S/N:	C2784A.cb	Mfr. Date:	2007.01.01	Diameter:	114.3 mm	Length:	
Shell MAWP:	21608.0 kPag	Shell MAWT:	93.0 C	Tube MAWP:		Tube MAWT:	
Inspection Date:	2012.04.06	Inspection Interval:	48.0 mth	Next UT Inspection Date:	2016.04.06		
IPVI Inspector:	PGY						
Vessel Disposition:	Fit For Service - As Is						

Justification for Assigned Interval:

Inspection Comment:

All UT readings above nominal - mill tolorence.
Set UT inspection interval at 4 years.

Generated On: Jun 08, 2012

Skystone ENGINEERING

Vessel Owner ID	Vessel Description	Vessel Location	Survey Date
A0573887	Lineheater Coil	100/01-01-111-11W6M	

Vessel Inspected Components

Inspected Component			Design Static Data				Survey Readings			Calculations			
ID	Description	Type	O.D.	Material Code	Nominal Thickness	Corrosion Allowance	Date	Reading Ave	Reading Min	Code Tmin	Short Term Corrosion Rate (mm/yr)	Long Term Corrosion Rate (mm/yr)	Calculated Remaining Life

Generated On: Jun 08, 2012

Vessel Owner ID	Vessel Description	Vessel Location	Survey Date
A0573887	Lineheater Coil	100/01-01-111-11W6M	

Piping Inspected Components

TML			Design Static Data				Survey		Calculations			
ID	Description	Type	Material Code	Nominal Pipe Size	Pipe Schedule	Nominal Thickness	Reading Ave	Reading Min	Code Tmin	Short Term Corrosion Rate (mm/yr)	Long Term Corrosion Rate (mm/yr)	Calculated Remaining Life

Generated On: Jun 08, 2012