



☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

Pro-Pak

Crate 1

p. 1/1

21151	1B	144723	3"	} spools
21151	1C	144723	3"	
21151	1C	145510	3"	

11151	30C	144723	6"	} spools
11151	31A	144723	6"	
11151	31C	144723	6"	
11151	24C	144723	6"	
11151	30A	144723	6"	
11151	25B	144723	6"	
11151	25A	144723	6"	
11151	31C	145510	6"	

11148	01C	12" S/S	45°	} Flange, 45°
11148	02C	12" S/S	45°	
11148	01D	12" S/S	45°	
11148	02D	12" S/S	45°	

-21151-21-10 (3/4x4 studs B7 21151 210/101)

~~\_\_\_\_\_~~

- 21151-01B (3" 600 spool)
- 21151-01C (3" 600 spool)
- 21151-25C (6" spool)
- 21151-27A (6" spool)
- 21151-33A (6" spool)
- 21151 240/81 (6" 45°) (sch 40 wpl 6)
- 21151 250/71 (6" 45° sch 40 wpl 6)
- 21151 360/80 (6" 45° sch 40 wpl 6)
- 21151 310/80 (6" 45° sch 40 wpl 6)
- 21147 3/40 (engine exhaust belows 2x)
- 11151 22A (spool) (5 NPS)
- 11151 28A (5 NPS spool)
- 11151 27A (6 NPS spool)
- 11151 33A (6 NPS spool)



☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

Pro Pak

pallet 2

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

110" x 3" galvanized cross bracing Q: 8)  
galvanized legs Q: 4)



**IPAC**  
SERVICES CORP.

☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

Pro-Pak

pallet 1

110" x 3" galvanized cross braces Q:8)  
galvanized legs Q:4)  
galvanized ladder cage Q:1)



**IPAC**  
SERVICES CORP.

☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

Pro Pak

crate #9

p1/1

shrouds

small x 4

large x 4



☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

Pro-P&K

crate #8

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

p1/1

- 11121 20/2140 1/2" x 2 1/2" bolts c/w nut/washer Q:8)
- 11121 150/1190 MC Bolt 16DIA-70 LG Full Thread SA-325 Q:4)
- 11161 3/370 5/8" x 3 1/2 BT studs c/w nuts Q:10)
- 11161 3/410 MC bolts 5/8" x 2" A-325 Bolt Only Q:12)
- 11161 3/440 1 3/8" 2H nut only Q:32)
- 11161 3/450 1" 2H nut only Q:24)
- 11161 3/590 1 3/8" 2H nut only Q:32)
- 11161 3/600 1 3/8" x 9" BT studs only Q:14)
- 11161 3/610 1 3/8" x 9" BT studs only Q:14)
- 11161 3/630 1 3/8" 2H nuts only Q:24)
- 11161 3/650 MC Bolt 1" x 3" A-325 c/w nut FLW Q:7)
- 11161 3/660 1 3/8" x 19" studs only Q:16)
- 11161 20/100 3/4" male x 1/2" female Flangecock for level gauge Q:1)
- 11161 30/90 2" check valve Horizontal Flow Threaded body SA-105 Q:2)
- 11161 30/100 4" 600 RF check valve SA-516-70 Q:1)
- 11161 70/80 2" Flex hose 305mm long 150 RF ends Q:1)
- 11161 70/90 2" Flex hose 457mm long 150 RF ends Q:1)
- 11161 90/30 4" 150 Wafer style Body A-216 Q:4)
- 11161 90/100 1" Standard Pipe Filter Q:1)
- 11161 100/150 1" Standard Pipe Filter Q:1)
- ~~11161~~
- 11161 70/100 3" Flex hose 305mm long 150 RF ends Q:1)

- misc Cat parts



☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

Pro-Pak

crate # 7

p1/2

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

11147 20/61 Plate Flange RF-4-A Q:1)  
21148 10/60 Grafoil gasket 380 O.D x 280 I.D Q:1)  
21151 3/210 Flex joint 21A Q:1)  
21151 3/211 Flex joint 21B Q:1)  
21151 3/340 3" 150 spool 925mm x 890mm Q:1)  
21161 3/10 1 1/2" JW Shunt Line c/w hose Q:1)  
21161 3/30 1 1/2" AW Shunt Line c/w hose Q:1)  
21161 3/30 Cat Strainer 155 Cone Q:1)  
21161 3/40 Cat Strainer 157 cone Q:1)  
21161 3/230 1 1/2" x 8" bolts for leveling Cat engine Q:2)  
21161 3/240 1 1/2" x 3" bolts for flywheel Adapter Q:12)  
21161 3/250 Coupling Q:1)  
21161 3/70 5/8" x 3 3/4" studs c/w nuts Q:24) BT  
21161 3/80 3/4" x 3 3/4" studs c/w nuts Q:4) BT  
21161 3/90 1 1/2" 300 Gasket Q:1)  
21161 3/100 2" 300 Gasket Q:4)  
21161 3/110 4" 150 gasket for engine crank Q:1)  
21161 3/120 5/8" x 3 1/2" studs/w/nuts for engine crank Q:8)  
21161 3/170 3/8" x 2" MC Bolts Q:8)  
21161 3/180 3/8" x 2" MC Bolts Q:8)  
11121 10/1650 3/4" x 1 7/8" Bolts c/w nut & washer Q:18)  
11121 20/2090 5/8" x 3 1/4" Bolts c/w nuts & washer Q:4)  
11121 40/1280 3/4" 1 7/8" Bolts c/w nuts & washer Q:4)  
~~11147 10/70 Grafoil gasket 455 O.D x 348 I.D Q:2)~~  
11147 10/90 3/8" x 2 1/4" c/w nuts/washer Q:24)  
11147 20/40 1 1/4" x 3" c/w nuts/washer Zinc Coated Q:24)  
11147 20/70 Grafoil gasket 3" 150 Q:1)  
11147 20/80 5/8" x 2 1/4" Bolts c/w nuts/washer Q:8)  
11148 10/60 Grafoil gasket 380 O.D x 280 I.D Q:1)  
11148 10/80 3/8" x 2 1/4" Bolts c/w nuts/washers Q:12)  
11148 20/60 3/8" x 2 1/4" Bolts c/w nuts/washers Q:12)  
11148 20/80 Grafoil gasket 380 O.D x 280 I.D Q:1)



**IPAC**  
SERVICES CORP.

☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

Pro-Pak

crate #7

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

p2/a

- 11151 180/120 6" 300 gasket SPWD Q:1)
- 11151 210/180 Garlock gasket 152mm x 89mm Q:2)
- 11151 220/40 Garlock gasket ~~(322)~~ 194mm x 143mm Q:2)
- 11151 240/50 3/4" x 4" studs c/w nuts B7 Q:8)
- 11151 240/60 3/4" x 6 1/2" studs c/w nuts B7 Q:8)
- 11151 250/50 3/4" x 4" studs c/w nuts B7 Q:8)
- 11151 250/60 3/4" x 6 1/2" studs c/w nuts B7 Q:8)
- 11151 270/91 Garlock gasket 194mm O.D x 143mm O.D Q:2)
- 11151 280/40 Garlock gasket 194mm O.D x 143mm O.D Q:2)
- 11151 300/50 3/4" x 4" c/w nuts B7 Q:8)
- 11151 300/60 3/4" x 6 1/2" c/w nuts B7 Q:8)
- 11151 310/50 3/4" x 4" c/w nuts B7 Q:8)
- 11151 310/60 3/4" x 6 1/2" c/w nuts B7 Q:8)
- 11151 330/101 Garlock gasket 194mm x 143mm Q:2)
- 11161 2/300 3/8" x 1 1/4" MC Bolts Q:40)
- 11161 3/210 3/8" nuts Q:40)
- 11161 3/220 3/8" lock washer Q:40)
- 11161 3/230 3/8" Flat washers Q:80)
- 11161 3/270 1 1/2" x 8" Fine thread bolts Q:6)
- 11161 3/280 1 1/2" x 2 3/4" Fine thread bolts Q:12)
- 11161 3/290 Fly wheel Adapter for Cat engine Q:1)
- 21147 20/30 Grafoil gasket 455 O.D x 348 I.D Q:2)
- 21148 20/60 Grafoil gasket 380 O.D x 280 I.D Q:1)



☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

Pro-Pak

crate #6

p1/1

21148 3/13 12" air intake Q:1)  
21151 3/41 24B 6" spool 1010 mm  
21151 3/42 24C 6" spool 400 mm  
21151 3/250 25A 6" spool 400 mm  
21151 3/310 30A 6" 150 537 mm  
21151 3/311 31A 6" 150 400 mm  
21151 3/312 31C 6" 150 538 mm  
21161 3/10 1 1/2" JW Shunt line c/w hose  
21161 3/20 1 1/2" AW Shunt line c/w hose



**IPAC**  
SERVICES CORP.

☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

Pro-Pak

crate #5

p1/1

[Redacted]

[Redacted]



☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

Pro-Pak

Crate 4

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

P111

11121 - 40/1390	( 5/8 X 2 (w/Nut & washer)	Q: 4
11121 - 40/1410	( 3/4 X 2 (w/Nut & washer)	Q: 2
11147 - 10/11	( Toolbox )	Q: 1
11147 10/60	( 26" 150 graffoil gasket )	Q: 4
11147 10/80	( 1 1/4 X 3 Cw Nut & washer	Q: 96
11147 20/30	( 26" 150 graffoil gasket )	Q: 1
11148 10/50	( 20" 150 graffoil gasket )	Q: 1
11148 10/70	( 1 1/8 X 2 3/4 (w/Nut & washer)	Q: 20
11148 20/70	( 1 1/8 X 2 3/4 Cw Nut & washer)	Q: 20
11148 30/40	( 1 1/4 X 3" Cw N & w	Q: 72
11148 40/100	( graffoil GHE-3	Q: 1
11148 40/110	( graffoil GHE-3	Q: 2
11161 3/50	( 3/8 X 2 bolts SP#27A )	Q: 8
11161 3/60	( 3/8 X 2 bolts SP#33A )	Q: 8
11161 3/70	( 5/8 X 3 3/4 B7 Studs & nuts )	Q: 16
11161 3/80	( 3/4 X 3 3/4 B7 w/ nuts )	Q: 8
11161 3/90	( 1 1/2" 300 gaskets 304SS	Q: 2
11161 3/100	( 2" 300 gaskets 304SS	Q: 2
11161 3/120	( 4" 150 gaskets 304SS	Q: 1
11161 3/130	( 5/8 X 3 1/2 B7 studs w/nuts	Q: 8
11161 3/180	( 3/8 X 2 bolts SP#22A	Q: 8
11161 3/190	( 3/8 X 2 bolts SP#28A	Q: 8
11161 3/240	( Exhaust bellows	Q: 1
21147 10/70	( 455 OD X 348 graffoil	Q: 2
21147 20/30	( 26" 150 graffoil	Q: 1
21148 20/50	( 20 150 graffoil	Q: 1



**IPAC**  
SERVICES CORP.

☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

Ro-Rak

Crate 3

P11



☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

Pro R&K

Crate 2

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

p1/2

11151	3/210	(Flex Joint) (457mm)
11151	3/211	(Flex Joint) (305mm)
21121	10/1650	( $\frac{3}{4}$ X $1\frac{7}{8}$ w/ Nut & washer) (Q:18)
21121	10/1770	( $\frac{7}{8}$ X $3\frac{1}{2}$ bolt w/ nuts & washer (Q:8)
21121	20/1210	( $\frac{3}{4}$ X 2 bolt w/ Nut & washer Q:16)
21121	20/12090	( $\frac{5}{8}$ X $3\frac{1}{4}$ w/ Nut & washer Q:4)
21121	40/1280	( $\frac{3}{4}$ X $1\frac{7}{8}$ w/ Nut & washer Q:4)
21121	50/1130	( $\frac{3}{8}$ X 1 w/ Nut & washer Q:4)
21121	50/1140	( $\frac{3}{8}$ X $1\frac{1}{2}$ w/ Nuts & washer zinc coated Q:10)
21121	60/2070	( $\frac{3}{4}$ X $2\frac{1}{2}$ w/ nuts & washer Q:4)
21121	80/2080	( $\frac{3}{4}$ X 2 w/ nuts & washer Q:4)
21147	10/180	( $1\frac{1}{4}$ X 3 w/ Nut & washer Q:96)
21147	10/190	( $1\frac{1}{4}$ X 3 w/ Nut & washer Q:24)
21147	20/40	( $1\frac{1}{4}$ X 3 w/ Nut & washer zinc coated Q:24)
21147	20/70	(4" 150 graffiti) (Q:1)
21148	10/70	( $1\frac{1}{8}$ X $2\frac{3}{4}$ w/ Nuts & washer Q:20)
21148	10/180	( $\frac{3}{8}$ X $2\frac{1}{4}$ w/ Nut & washer Q:12)
21148	10/120	( $1\frac{1}{8}$ X $2\frac{3}{4}$ w/ Nut & washer Q:20)
21148	20/70	( $1\frac{1}{8}$ X $2\frac{3}{4}$ w/ Nut & washer Q:20)
21148	20/80	( $\frac{3}{8}$ X $2\frac{1}{4}$ w/ Nut & washer Q:12)
21148	20/120	( $1\frac{1}{8}$ X $2\frac{3}{4}$ w/ Nuts & washer Q:20)
21148	30/40	( $1\frac{1}{4}$ X 3 w/ Nut & washer Q:72)
21148	60/10	( $\frac{1}{2}$ X $1\frac{1}{4}$ w/ Nut & washer Q:16)
21148	60/20	( $\frac{3}{8}$ X $1\frac{1}{4}$ w/ Nut & washer Q:40)
21148	60/30	( $\frac{3}{8}$ flat washers Q:80)
21148	60/40	( $\frac{3}{8}$ X $1\frac{1}{4}$ bolt w/ Nuts & washer Q:16)
21151	220/40	(Garlock gasket 194 OD X 143 ID) (3M)
21151	270/91	(Garlock gasket 194 OD X 143 ID 3M) (Q:2)
21151	280/40	(Garlock gasket 194 OD X 143 ID 3M) (Q:2)
21151	330/101	(Garlock gasket 194 OD X 143 ID 3M) (Q:2)
21151	340/51	(3" 150 SPUD) (Q:2)
21161	20/30	(LG-1561 Flat glass level gauge)
21161	20/80	(LG-1561 Gauge Case for level gauge)
21161	20/80	(Flex hose) (2" 305mm)



**IPAC**  
SERVICES CORP.

☐ **Head Office**  
8701 - 102 Street  
Clairmont, AB T8X 5G8  
Bus: (780) 532-7350  
Fax: (780) 532-7769

For a complete list of operation centers visit: [www.ipacservices.com](http://www.ipacservices.com)

Pm-P&K

Crate 2

p2/a

21161	90/30	( 4" ISO wafer check )	
11121	20/2060	( 5/8 x 2 CW / Nut & washer )	Q : 8
11121	40/1290	( 5/8 x 2 CW / Nut & washer )	Q : 16
11147	20/61	( Plate Flange )	RF-4-A