P.O. Box 736
Grande Prairie, AB.
T8V 3R5
Fax # 780 539-1777
Toll Free 1-866-NDT XRAY
Ph. # 780 539-0000

INSPECTRUM TESTING INC

Non- Destructive Inspection

ND 10329

Client: ARC RESOURCES
Location: 13-27 Date: MAY-30/08
Item Inspected: HEATER COIL

AFE#
P.O.#
Job#

Job Scope UT ELBOW FOR THICKNESS

INSPECTION RESULTS: S:N - C2784A - CB LSD: 13-27

ELBOW # 1	ELBOW # 2	ELBOW # 3	ELBOW # 4
S1 - 0.521	S1 - 0.519	S1 - 0.518	S1 - 0.514
S2 - 0.516	S2 - 0.521	S2 - 0.531	S2 - 0.515
S3 - 0.516	S3 - 0.523	S3 - 0.520	S3 - 0.527
S4 - 0.522	S4 - 0.521	S4 - 0.531	S4 - 0.531
S5 - 0.521	S5 - 0.526	S5 - 0.527	S5 - 0.516

ELBOW # 5	ELBOW # 6	ELBOW # 7	ELBOW # 8
S1 - 0.528	S1 - 0.533	S1 - 0.531	S1 - 0.533
S2 - 0.531	S2 - 0.534	S2 - 0.520	S2 - 0.524
S3 - 0.537	S3 - 0.533	S3 - 0.518	S3 - 0.526
S4 - 0.533	S4 - 0.533	S4 - 0.516	S4 - 0.528
S5 - 0.534	S5 - 0.533	S5 - 0.531	S5 - 0.531

4" sch 160
Nom :- 0.531

* all welds and piping are sch. 160

Inspection Performed By:
Steve Shiram (Print)
SNT-TC-1A II
CGSB L
CGSB#
(Signature)

Consumables:
1 HR Rig.

Unit# Km 0
In Out
In Out
Personnel S.S M.P

I am in full agreement of report contents
Client Representative Noel Bureau

Cost Estimate:
$ 0 + Tax
(Invoice to follow by mail)